DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION

Juneau Automated Flight Service Station 9230 Cessna Drive Juneau AK 99801-9377

ISSUED: 4/16/04 EFFECTIVE: 4/16/04 Juneau Automated Flight Service Station LETTER TO AIRMEN NO. 04-1

SUBJECT: Yakutat Airport Runway Closure

CANCELLATION: 9/1/04

Yakutat Airport runway 11/29 will be closed until approximately August 31, 2004 for re-grading, re-surfacing and improvement of the runway safety areas. The runway has been marked with standard visual indicators for a closed runway (X's)

The runway 11/29 instrument landing system (ILS), runway lights, approach lights and visual approach slope indicators (VASI) will also be shut down during the construction project.

Runway 2/20 is maintained and available for use. Pilot controlled runway lights are available on frequency 123.6 Mhz.

Instrument approach procedures using VOR, DME, NDB, and GPS will continue to be available.

Because conditions may change, pilots should check with the nearest Flight Service Station or DUATS for current NOTAMS. The 11/29 runway closure has been published in the current Alaska Supplement effective 4/15/04.

Paulette L. Coleman

Paulote & Colaman

Air Traffic Manager, Juneau Automated Flight Service Station